


XPEL **FUSION PLUS PLASTIC & TRIM** is a flexible and thin ceramic coating that helps protect your vehicles plastics and rubber trim from fading due to damaging UV rays. XPEL FUSION PLUS PLASTIC & TRIM also helps protect against staining on your plastics and trim surfaces

**PRODUCT  
CONSTRUCTION**



**GENERAL CHARACTERISTICS**

PROPERTIES	INFORMATION
Bottle Size	50 ml
Shelf Life	1 Year from ship date when unopened and stored dry at 64 Degrees F to 73 Degrees F
Application	Hand Application with supplied foam applicator and microsuede towel
Appearance	Clear
Dry Time	30 - 60 minutes
Cure Time	Initial cure in 4 hours   Full cure in 3 Days

**TARGET  
APPLICATIONS**

XPEL FUSION PLUS PLASTIC & TRIM Ceramic Coating adds ease of mind with protecting your vehicles plastics and trim. All designed to withstand years of protection.



**Plastic & Trim**



Toll Free: (800) 447-9928  
International: +1 (210) 678-3700  
Fax: (210) 678-3701  
[www.xpel.com](http://www.xpel.com)

Notice: The representations of performance and suitability for use contained in this Technical Data Sheet are meant only as a guide. Since only the user is aware of the specific conditions in which the product is to be used, it is the user's responsibility to determine whether the product is suitable for that intended use.

## APPLICATION INSTRUCTIONS

The below are our recommended instructions for prepping and installing XPEL **FUSION PLUS** PLASTIC & TRIM. This product is a professionally applied product only. The below is only a basic guideline for application. Please do not attempt to install without proper training and XPEL Certification.

### STEP 1



Ensure the plastic and trim surfaces are extremely clean, dry, free from debris and contaminants

### STEP 2



Apply **FUSION PLUS PLASTIC & TRIM** by hand using the supplied Foam Applicator and Microsuede Towel.

### STEP 3



After Flash (appx 10-45 seconds), wipe with a clean microfiber towel.

Remove any left over coating with a new clean microfiber towel.

### STEP 4



Allow the surface to fully dry before use.

Initial Dry Time: 30 - 60 Minutes  
Before getting wet: Minimum 4 hours  
Full Cure: 24 Hours



Toll Free: (800) 447-9928  
International: +1 (210) 678-3700  
Fax: (210) 678-3701  
[www.xpel.com](http://www.xpel.com)

Notice: The representations of performance and suitability for use contained in this Technical Data Sheet are meant only as a guide. Since only the user is aware of the specific conditions in which the product is to be used, it is the user's responsibility to determine whether the product is suitable for that intended use.