


XPEL **FUSION PLUS WHEEL & CALIPER** is tested and proven to withstand the wear and tear and the constant heat that your vehicles wheels and calipers go through on a daily basis. With a protective hydrophobic layer, maintaining your wheels and calipers, just became easier.

PRODUCT CONSTRUCTION



GENERAL CHARACTERISTICS

PROPERTIES	INFORMATION
Pencil Hardness	9H
Bottle Size	50 mL
Shelf Life	1 Year from ship date when unopened and stored dry at 64 Degrees F to 73 Degrees F
Application	Foam Block with microsuede towel
Appearance	Clear
Dry Time	6 Hours before getting wet
Cure Time	Full cure hardness 3 days

TARGET APPLICATIONS

XPEL FUSION PLUS WHEEL & CALIPER Ceramic Coating adds depth, improves shine and surface clarity while protecting your vehicle from the elements with its super hydrophobic formula. All designed to withstand years of driving.



Toll Free: (800) 447-9928
International: +1 (210) 678-3700
Fax: (210) 678-3701
www.xpel.com

Notice: The representations of performance and suitability for use contained in this Technical Data Sheet are meant only as a guide. Since only the user is aware of the specific conditions in which the product is to be used, it is the user's responsibility to determine whether the product is suitable for that intended use.

**APPLICATION
INSTRUCTIONS**

The below are our recommended instructions for prepping and installing XPEL **FUSION PLUS** WHEEL & CALIPER. This product is a professionally applied product only. The below is only a basic guideline for application. Please do not attempt to install without proper training and XPEL Certification.

STEP 1



If required, paint correction must be done before installing FUSION PLUS WHEEL & CALIPER.

If contaminated use clay bar to clean paint/surface

STEP 2



Wash and completely dry surfaces to be ceramic coated with FUSION PLUS

STEP 3



Complete a final wipe with 50% Isopropyl Alcohol to water mix (50/50 Water /Alcohol).

Spray fine mist on the paint and then wipe clean with a clean new microfiber

STEP 4



Apply FUSION PLUS by hand using the supplied Foam Applicator and Microsuede Towel.

Recommended to apply in 2'x2' sections

STEP 5



After Flash (appx 10-45 seconds), wipe with a clean microfiber towel.

Remove any left over coating with a new clean microfiber towel.

*If there is any leftover residue, use a microfiber with light mist of water and buff off

STEP 6



Allow at least 6 hours before getting surface wet.

The coating will continue to cure over the next 3 days to 9H hardness



Toll Free: (800) 447-9928
International: +1 (210) 678-3700
Fax: (210) 678-3701
www.xpel.com

Notice: The representations of performance and suitability for use contained in this Technical Data Sheet are meant only as a guide. Since only the user is aware of the specific conditions in which the product is to be used, it is the user's responsibility to determine whether the product is suitable for that intended use.