


XPEL **FUSION PLUS** PAINT & PPF is a flexible and thin, 9H ceramic coating, purposely developed to perform with PPF (paint protection film) and painted surfaces. PAINT & PPF offers unrivaled gloss, superior hydrophobic protection, and improved scratch resistance with a single layer application.

PRODUCT CONSTRUCTION



GENERAL CHARACTERISTICS

PROPERTIES	INFORMATION
Pencil Hardness	9H
Bottle Size	50 mL
Shelf Life	1 Year from ship date when unopened and stored dry at 64 Degrees F to 73 Degrees F
Application	Foam Block with microsuede towel
Appearance	Clear
Temperature Resistance	>760 Degrees Celsius
Mandrel Bend	(ASTM D522) 0% at 180 Degree Rotation
Dry Time	6 Hours before getting wet
Cure Time	Full cure hardness 3 days

TARGET APPLICATIONS

XPEL FUSION PLUS Ceramic Coating adds depth, improves shine and surface clarity while protecting your vehicle from the elements with its super hydrophobic formula. All designed to withstand years of driving.



PAINT PROTECTION FILM



PAINT



Toll Free: (800) 447-9928
 International: +1 (210) 678-3700
 Fax: (210) 678-3701
www.xpel.com

Notice: The representations of performance and suitability for use contained in this Technical Data Sheet are meant only as a guide. Since only the user is aware of the specific conditions in which the product is to be used, it is the user's responsibility to determine whether the product is suitable for that intended use.

APPLICATION INSTRUCTIONS

The below are our recommended instructions for prepping and installing XPEL **FUSION PLUS** PAINT & PPF. This product is a professionally applied product only. The below is only a basic guideline for application. Please do not attempt to install without proper training and XPEL Certification.

STEP 1



If required, paint correction must be done before installing FUSION PLUS.

If contaminated use clay bar to clean paint/surface

STEP 2



Wash and completely dry surfaces to be ceramic coated with FUSION PLUS

STEP 3



Complete a final wipe with 50% Isopropyl Alcohol to water mix (50/50 Water /Alcohol).

Spray fine mist on the paint and then wipe clean with a clean new microfiber

STEP 4



Apply FUSION PLUS by hand using the supplied Foam Applicator and Microsuede Towel.

Recommended to apply in 2'x2' sections

STEP 5



After Flash (appx 10-45 seconds), wipe with a clean microfiber towel.

Remove any left over coating with a new clean microfiber towel.

*If there is any leftover residue, use a microfiber with light mist of water and buff off

STEP 6



Allow at least 6 hours before getting surface wet.

The coating will continue to cure over the next 3 days to 9H hardness



Toll Free: (800) 447-9928
International: +1 (210) 678-3700
Fax: (210) 678-3701
www.xpel.com

Notice: The representations of performance and suitability for use contained in this Technical Data Sheet are meant only as a guide. Since only the user is aware of the specific conditions in which the product is to be used, it is the user's responsibility to determine whether the product is suitable for that intended use.