


XPEL **FUSION PLUS UPHOLSTERY** Ceramic Coating offers superior protection for your fabric seats, carpet, leather and vinyl surfaces. XPEL FUSION PLUS UPHOLSTERY protects your surfaces while retaining the factory feel and natural finish.

PRODUCT CONSTRUCTION



GENERAL CHARACTERISTICS

PROPERTIES	INFORMATION
Bottle Size	16 oz
Shelf Life	1 Year from ship date when unopened and stored dry at 64° F to 73° F
Application	Spray Bottle with hand trigger and microfiber towel applied between 50° F to 90° F
Appearance	Clear
Dry Time	30 - 60 minutes
Cure Time	Full cure in 24 hours

TARGET APPLICATIONS

XPEL FUSION PLUS UPHOLSTERY Ceramic Coating adds ease of mind with stain and spill resistant hydrophobic properties on your fabric, carpet, leather and vinyl surfaces. All designed to withstand years of protection.



Toll Free: (800) 447-9928
 International: +1 (210) 678-3700
 Fax: (210) 678-3701
www.xpel.com

Notice: The representations of performance and suitability for use contained in this Technical Data Sheet are meant only as a guide. Since only the user is aware of the specific conditions in which the product is to be used, it is the user's responsibility to determine whether the product is suitable for that intended use.

APPLICATION INSTRUCTIONS

The below are our recommended instructions for prepping and installing XPEL **FUSION PLUS** UPHOLSTERY. This product is a professionally applied product only. The below is only a basic guideline for application. Please do not attempt to install without proper training and XPEL Certification.

STEP 1



Ensure all fabric, carpet, leather and vinyl are clean and dry before applying product.

STEP 2



Test an inconspicuous area to confirm compatibility before applying to entire surface area

STEP 3



For Fabric and Carpet: Spray product onto carpet or fabric in an X pattern, covering the surface completely. If residue remains, use dry sponge or microfiber to massage product into the surface

For Leather and Vinyl: Spray product onto microfiber towel, then wipe the surface until no residue remains

STEP 4



Allow the surface to fully dry before use.

Carpet and Fabric: Approximately 60 minutes

Leather and Vinyl: Approximately 30 minutes



Toll Free: (800) 447-9928
International: +1 (210) 678-3700
Fax: (210) 678-3701
www.xpel.com

Notice: The representations of performance and suitability for use contained in this Technical Data Sheet are meant only as a guide. Since only the user is aware of the specific conditions in which the product is to be used, it is the user's responsibility to determine whether the product is suitable for that intended use.